

NOTICE OF COMPLETION
AND
AUTHORIZATION TO APPLY THE UL MARK



02/19/2014

Spellman High Voltage Electronics Corp
Mr. David Keen
475 Wireless Blvd
Hauppauge Ny 11788-3951, Us

Our Reference: File E242584, Vol. X1 Project Number 4786284089
Your Reference: N/A
Project Scope: UL/C-UL Reports for Component Safety Investigation to IEC 60601-1, 3rd Edition with Risk Management for X-Ray Generator, Model: PDM90PN900, under UL Report E242584-A28.

Dear Mr. David Keen:

Congratulations! UL's investigation of your product(s) has been completed under the above Reference Number and the product was determined to comply with the applicable requirements. This letter temporarily supplements the UL Follow-Up Services Procedure and serves as authorization to apply the UL Mark at authorized factories under UL's Follow-Up Service Program. To provide your manufacturer(s) with the intended authorization to use the UL Mark, you must send a copy of this notice to each manufacturing location currently authorized under File E242584, Vol. X1 and including any special instructions as indicated in the addendum to this letter.

Records in the Follow-Up Services Procedure covering the product are now being prepared and will be sent in the near future. Until then, this letter authorizes application of the UL Mark for 90 days from the date indicated above.

Additional requirements related to your responsibilities as the Applicant can be found in the document "Applicant responsibilities related to Early Authorizations" that can be found at the following web-site:

<http://www.ul.com/EAResponsibilities>

Any information and documentation provided to you involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL.

We are excited you are now able to apply the UL Mark to your products and appreciate your business. Feel free to contact me or any of our Customer Service representatives if you have any questions.

Very truly yours,

Michael A. Lavorata
631-546-3290
Senior Project Engineer
Michael.A.Lavorata@ul.com

Reviewed by:

William R. Carney
847/664-1088
Chief Engineer Director I
William.R.Carney@ul.com

NBK99BD-711E89